



DELHI POLLUTION CONTROL COMMITTEE

(Government of N.C.T. of Delhi) 4th & 5th Floor, ISBT Building
Kashmere Gate, Delhi 110006
(Visit us at <https://www.dpccocmms.nic.in>)



Form 4 (See Rule 13) ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier health care facility(HCF), or common bio-medical waste treatment facility (CBWTF)]

Return No : 15337836

Period : 2025

1. Particulars of the Occupier	
(i) Name of the authorized person (Occupier or operator of facility):	PRABAL PRATAP SINGH JADON
(ii) Name of HCF or CBMWTF:	SMS WATER GRACE BMW PVT. LTD.
(iii) Address for Correspondence:	DELHI JAL BOARD, SEWAGE TREATMENT PLANT NILOTHI
(iv) Address of Facility:	DELHI JAL BOARD, SEWAGE TREATMENT PLANT NILOTHI
(v) Tel. No.:	8744076042
(vi) Fax. No.:	-
(vii) E-mail ID:	prabal.singh@smsl.co.in
(viii) URL of Website:	www.smsdelhibmw.co.in
(ix) GPS coordinates of HCF of CBMWTF:	28.65N & 77.04E
(x) Ownership of HCF or CBMWTF:	Private
(xi) Status of Authorization under the BMW (Management and Handling) Rules:	Authorization No.: 27772996 Valid Upto: 13/08/2029
(xii) Status of Consents under Water Act and Air Act.:	Valid Upto: 24/01/2029
2. Type of Health Care Facility	
HCF/CBMWTF Type:	CBMWTF
(i) Number healthcare facilities covered by CBMWTF:	6520
(ii) No. of beds covered by CBMWTF:	38261
(iii) Installed treatment and disposal capacity of CBMWTF:	28800
(iv) Quantity of BMW treated or disposal by CBMWTF:	17438

3. Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	Yellow Category: 2545809 Red Category: 2926248 White Category: 184718 Blue Category: 707994 General Solid Waste: 0																						
4. Details of the Storage, Treatment, Transportation, Processing and Disposal Facility Details																							
(i) Details of the on-site storage facility:	Size: 900 Metric Tonnes/Day Capacity: 25 Metric Tonnes/Day Provision of on-site storage: Closed Room																						
(ii) Disposal Facility:	<table border="1"> <thead> <tr> <th>Type of Treatment Equipment</th> <th>Number of Units</th> <th>Capacity(Kg/day)</th> <th>Quantity Treated or Disposed(Kg/annum)</th> </tr> </thead> <tbody> <tr> <td>Incinerators</td> <td>2</td> <td>12000 kg</td> <td>2545809</td> </tr> <tr> <td>Autoclaves</td> <td>2</td> <td>16800 kg</td> <td>2926248</td> </tr> <tr> <td>Shredder</td> <td>2</td> <td>13200 kg</td> <td>2926248</td> </tr> <tr> <td>Chemical Disinfection</td> <td>1</td> <td>9600 kg</td> <td>707994</td> </tr> </tbody> </table>	Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)	Incinerators	2	12000 kg	2545809	Autoclaves	2	16800 kg	2926248	Shredder	2	13200 kg	2926248	Chemical Disinfection	1	9600 kg	707994		
Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)																				
Incinerators	2	12000 kg	2545809																				
Autoclaves	2	16800 kg	2926248																				
Shredder	2	13200 kg	2926248																				
Chemical Disinfection	1	9600 kg	707994																				
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	3534000.0																						
(iv) No of vehicles used for collection and transportation of BMW:	50																						
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum	<table border="1"> <thead> <tr> <th>Type of waste</th> <th>Quantity Generated</th> <th>Where disposal</th> </tr> </thead> <tbody> <tr> <td>Ash</td> <td>279400</td> <td>Landfill</td> </tr> <tr> <td>ETP Sludge</td> <td>12100</td> <td>Incineration</td> </tr> </tbody> </table>	Type of waste	Quantity Generated	Where disposal	Ash	279400	Landfill	ETP Sludge	12100	Incineration													
Type of waste	Quantity Generated	Where disposal																					
Ash	279400	Landfill																					
ETP Sludge	12100	Incineration																					
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	SMS WATER GRACE BMW PVT LTD																						
5. Do you have BMW management committee:	no																						
6. Training Conducted on BMW Details																							
(i) Number of training conducted on BMW Management:	12																						
(ii) Number of personnel trained:	600																						
(iii) Number of personnel trained at the time of induction:	0																						
(iv) Number of personnel not undergone any training so far:	0																						
(v) Whether standard manual for training is available:	yes																						
(vi) Any other information:	PPT based training is provided																						
7. Details of the accident occurred																							
(i) No. of accident occurred:	0																						
(ii) Number of the persons affected:	0																						
(iii) Remedial Action taken:	Nil																						
(iv) Any Fatality occurred, details:	Nil																						
8. Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	Yes																						
Details of Continuous online emission monitoring systems installed:	Drexel Electronics and Engineering Products Private Limited																						
9. Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	Nil																						
10. Is the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	Yes																						

11. Any other relevant information:	APCD attached with Incinerator
12. Certified that the above report is for the period from:	JANUARY-2025 TO DECEMBER-2025

Name and Signature of the Head of the Institution

Date :08/05/2026

Place : NORTH WEST

